

## Long Road Racing

2668 Peachtree Road = Statesville, NC 28625 = Phone: 980-223-8547

Since 2001 LongRoadRacing.com

# Global MX-5 Cup Car Technical Service Bulletin #06-27-2017

### **<u>REQUIRED</u>**: 2017 Global MX-5 Update: **Cooling hose clamp** update effective immediately


#### This TSB describes:

1. A chance of the lower radiator hose clamp may become dislodged (see diagram). The factory spring style clamp is being replaced with a standard stainless steel screw style clamp. This ONE clamp is a mandatory change, but all other water hose clamps may be changed to a stainless steel screw style clamps at your option. Purchase the clamp(s) locally.

#### Installation:

1. Follow all Mazda service manual instructions for safety, removal and replacement of the water hose clamp(s).

#### **Diagram:**



If you have any questions about this Technical Bulletin, please contact Glenn Long at: <u>GLENN@LongRoadRacing.COM</u> or 919-614-4797

2668 Peachtree Road, Statesville, NC 28625 - Phone: 980-223-8547