

## Global MX-5 Cup Car Technical Service Bulletin #06-27-2017

**REQUIRED:** 2017 Global MX-5 Update: **Cooling hose clamp** update effective immediately


This TSB describes:

1. A chance of the lower radiator hose clamp may become dislodged (see diagram). The factory spring style clamp is being replaced with a standard stainless steel screw style clamp. **This ONE clamp is a mandatory change**, but all other water hose clamps may be changed to a stainless steel screw style clamps at your option. Purchase the clamp(s) locally.

Installation:

1. Follow all Mazda service manual instructions for safety, removal and replacement of the water hose clamp(s).

Diagram:



If you have any questions about this Technical Bulletin, please contact Flis Performance at: Ashli@FlisPerformance.com or 386-256-7021