

## Mazda MX-5 Cup Car Technical Service Bulletin #2022-04-14

### Optional: Mazda MX-5 Cup Radiator Cap Safety Wire Hole(s)

This TSB describes: Update from previous TBS #2019-07-27. Updated information from 2022-04-14 below in RED.

The purpose of this TSB is to allow competitors to drill a hole in each ear(s) of either homologated radiator cap per the picture below. The competitor may then safety-wire the cap if desired. No other modifications to the radiator cap or use of the safety wire is permitted.

**Competitors are solely responsible for attaching the safety wire properly. If the wire is attached to the upper water hose clamp, we encourage competitors to ensure the clamp is tight. We have seen teams that have not tightened the clamp properly and this resulted in upper hose failure.**

This TSB takes effect on July 27, 2019



For any questions or concerns, please contact us:

Flis Performance

Ashli Richardson

386-256-7021

[ashli@flisperformance.com](mailto:ashli@flisperformance.com)