



Long Road Racing

2668 Peachtree Road ▪ Statesville, NC 28625 ▪ Phone: 980-223-8547

Since 2001

LongRoadRacing.com

Global MX-5 Cup Car Technical Service Bulletin #05-23-2017


Optional: 2017 Global MX-5 Update: Front Sway bar mounting hardware

This TSB describes:

1. The front sway bar mounting bracket may become stressed or fatigued, you have the option of using a larger diameter washer (see picture below).

Installation:

1. Remove and replace front sway bar nut and washer, replace with a larger diameter washer. Use thread sealant and torque the nut to 15 – 18 foot pounds



If you have any questions about this Technical Bulletin, please contact Glenn Long at:

GLENN@LongRoadRacing.COM or 919-614-4797