



Global MX-5 Cup Car Technical Service Bulletin #10-11-2017 — UPDATED INFORMATION ON JUNE 25, 2019

Optional*: 2017 Global MX-5 Update: Front sway bar end link washer placement

This TSB describes:

1. The front sway bar end link attachment washers' sequence, may be altered from how the car was delivered which are 4 in total per side of the car. The total number of four washers may not change per side, but their location (top to bottom or bottom to top) may. The homologated washer is still the only allowed washers.



If you have any questions about this Technical Bulletin, please contact Flis Performance at: ashli@flisperformance.com or 386-256-7021