



Global MX-5 Cup Car Technical Service Bulletin #06-26-2017

REQUIRED: 2017 Global MX-5 Update: Clutch and pressure plate upgrades are effective immediately

This TSB describes:

1. Due to enhanced power levels, the stock clutch is being replaced with Mazda P/N **0000-02-5006-SS**. The kit includes a new disk, pressure plate and alignment tool. It is suggested to replace the throw-out bearing at the same time Mazda P/N **LF01-16-510**.
2. The kit is currently in stock and available for purchase from Mazda Competition Parts 1-800-435-2508.

Installation:

1. Follow all Mazda service manual instructions for safety, removal and replacement of the clutch assembly.

If you have any questions about this Technical Bulletin, please contact Flis Performance at: Ashli@FlisPerformance.com or 386-256-7021