



Global MX-5 Cup Car Technical Service Bulletin #05-23-2018A


Optional: 2016 & 2017 Global MX-5 Update: Headlight leveling sensor

This TSB describes:

1. The headlight leveling sensor and sensor harness may be deleted.

Installation:

1. On 2016 and 2017 chassis' is now permitted to remove the headlight leveling sensor (N243-51-22ZA or B) and harness (N243-67-SH0A) from the left rear lower control arm.



(C) 2013 MAZDA Motor Corporation

If you have any questions about this Technical Bulletin, please contact Flis Performance at:
Ashli@FlisPerformance.com or 386-256-7021