




Global MX-5 Cup Car Technical Service Bulletin #01-24-2019

Optional: Global MX-5 Cup Steering column update to 2019 (tilt and telescoping) specifications

This TSB describes:

Optional changes to the GMX-5 cup car steering column with the addition of the telescoping feature to assist with driver comfort.

1. Part number ND6N-32-100 (2019+ Model year tilt & telescoping steering column) may now be substituted for NA1J-32-100 (2016 – 2018 tilt steering column). When updating to the 2019 style column, you will also need three additional parts. Mazda part numbers:
 - a. 0000-08-D230 Updated MXL2 mount
 - b. 0000-08-D234 Modified start/stop wiring harness
 - c. 0000-08-D235 Fire bottle line



Installation:

Follow all of the Mazda factory service manual procedures

If you have any questions about this Technical Bulletin, please contact Flis Performance at: ashli@flisperformance.com or 386-256-7021