



Mazda MX-5 Cup Technical Service Bulletin #2020-12-02 – (Optional)

TSB – Homologated Ballast Box:

Mazda MX-5 Cup Competitors,

With the Odyssey PC-1200 Battery being the only battery permitted in the 2021 Mazda MX-5 Cup series, competitors may remove the Homologated Ballast box and lid from their MX-5 Cup Car. It is not permitted to remove just the ballast box or remove just the lid individually. The Homologated ballast box must be used if ballast is required and the only permitted location for the ballast is within the ballast box.

If you are running a Cool Suit and have removed the ballast box, you must use the right-side seat plate bracket 0000-08-5111-RT bolted securely to the factory seat holes.



Corresponding rule changes will be incorporated into the 2021 Mazda MX-5 Cup rule book reflecting the above. If you have any questions or concerns, please contact us:

Flis Performance

Ashli Richardson

386-256-7021

ashli@flisperformance.com



PRESENTED BY: **BFGoodrich**

